

# Lock-up Cylinder/Double Acting, Single Rod

# Series CL1 Ø40, Ø50, Ø63, Ø80, Ø100 Ø125, Ø140, Ø160



# Construction





\* The numbers are the same as the "Construction" of the Best Pneumatics No.3 Series CL1.

#### Spal Kit Liet

Jean Kit List						
No.	Description	Material	Note			
CL1ø40 to ø100						
25	Rod seal					
A	Cushion seal					
B	Piston seal	NBR				
(C)	Cushion valve seal					
D	Cylinder tube gasket					
CL1ø125 to ø160						

27)	Rod seal						
E	Wiper ring						
F	Piston seal						
G	Valve seal						
$\overline{\mathbb{H}}$	Tube gasket	NBR					
J	Retaining plate gasket						
K	Cushion seal						
L	Guide gasket	]					
М	Piston gasket						

K, L and M are non-replaceable parts, so they are not included in the seal kit.


## Replacement Parts: Seal Kit

Bore size (mm)	Kit no.	Contents
40	CL40-PS	
50	CL50-PS	
63	CL63-PS	
80	CL80-PS	
100	CL100-PS	
125	CL125-PS	
140	CL140-PS	
160	CL160-PS	

- \* Since the lock section for Series CL1 is normally replaced as a unit, kits are for the cylinder section only. These can be ordered using the order number for each bore size.
- \* Seal kit includes a grease pack (ø40, ø50: 10 g, ø63, ø80: 20 g, ø100: 30 g, ø125 to ø160: 40 g).
- Order with the following part number when only the grease pack is needed.
- Grease pack part no.: GR-S-010 (10 g), GR-S-020 (20 g)
- \* As for the center trunnion type, it is very difficult to adjust the position of the trunnion bracket and the center of the axis.

Therefore repair at SMC is recommended.

### Replacement Parts: Lock-up Unit



\* Consult with SMC when replacing the lock-up unit with a bore size of ø125 to ø160.

